



Scanner Reset Codes

The scanner may inadvertently clear the scanned data if the UT 2122 Factory Defaults bar code is scanned. Do not scan the UT 2122 Factory Defaults bar code on the Quantity Card at any time. To ensure that the scanner functions properly, please scan the bar codes provided below in the order shown.



Scan First: Factory Defaults



Scan Second: Disable Auto Download



Scan Third: Enable XML Format



Scan Fourth: ACK Mode On